

**South Carolina Law Enforcement Division - Status Records**



Date Range From 01/01/2009 To 04/15/2010  
 DataMaster (BAC/DMT) Serial Number - 117407  
 Report Date - 4/15/2010

Legend I - Incomplete  
 R - Refusal  
 V - Invalid Sample  
 X - Interference Detected

| <u>Serial Number</u> | <u>Loc Number</u> | <u>Date/Time</u>      | <u>Status Record</u>           | <u>Status Info</u> |
|----------------------|-------------------|-----------------------|--------------------------------|--------------------|
| 117407               | SC0100100         | 3/15/2009 3:59:20 AM  | PUMP ERROR                     |                    |
| 117407               | SC0100100         | 3/15/2009 4:08:09 AM  | BLANK ERROR                    |                    |
| 117407               | SC0100100         | 4/11/2009 11:31:46 PM | INTERFERENCE DETECTED          |                    |
| 117407               | SC0100100         | 4/11/2009 11:38:27 PM | INTERFERENCE DETECTED          |                    |
| 117407               | SC0100100         | 4/16/2009 1:21:45 AM  | SIMULATOR TEMPERATURE TOO LOW  |                    |
| 117407               | SC0100100         | 6/4/2009 11:47:34 PM  | INTERNAL STANDARD OUT OF RANGE |                    |
| 117407               | SC0100100         | 6/24/2009 12:28:06 AM | SIMULATOR TEMPERATURE TOO LOW  |                    |
| 117407               | SC0100100         | 6/28/2009 3:00:08 AM  | PUMP ERROR                     |                    |
| 117407               | SC0100100         | 6/28/2009 3:23:49 AM  | INTERFERENCE DETECTED          |                    |
| 117407               | SC0100100         | 6/28/2009 3:26:47 AM  | INTERFERENCE DETECTED          |                    |
| 117407               | SC0100100         | 7/4/2009 3:40:42 AM   | PUMP ERROR                     |                    |
| 117407               | SC0100100         | 7/7/2009 7:50:40 PM   | BLANK ERROR                    |                    |
| 117407               | SC0100100         | 7/13/2009 8:56:52 PM  | INVALID SAMPLE DETECTED        |                    |
| 117407               | SC0100100         | 7/25/2009 6:56:47 PM  | PUMP ERROR                     |                    |
| 117407               | SC0100100         | 8/13/2009 1:54:25 AM  | RFI DETECTED                   |                    |
| 117407               | SC0100100         | 10/9/2009 10:04:28 PM | COMMUNICATION ERROR            |                    |
| 117407               | SC0100100         | 10/17/2009 9:48:29 PM | PUMP ERROR                     |                    |
| 117407               | SC0100100         | 10/31/2009 9:05:20 PM | INVALID SAMPLE DETECTED        |                    |
| 117407               | SC0100100         | 10/31/2009 9:30:11 PM | INVALID SAMPLE DETECTED        |                    |
| 117407               | SC0100100         | 11/2/2009 12:53:50 AM | COMMUNICATION ERROR            |                    |
| 117407               | SC0100100         | 2/20/2010 5:14:43 AM  | SUCK BACK ERROR                |                    |
| 117407               | SC0100100         | 3/18/2010 4:41:41 AM  | SUCK BACK ERROR                |                    |
| 117407               | SC0100100         | 4/9/2010 3:08:20 AM   | SUCK BACK ERROR                |                    |

**THIS REPORT REPRESENTS TRUE AND CORRECT COPIES OF THE ORIGINAL DOCUMENTS MAINTAINED BY SLED IN THE NORMAL COURSE OF BUSINESS.**

**DEBORAH H. BANKS, LIEUTENANT  
 SUPERVISORY SPECIAL AGENT  
 IMPLIED CONSENT DEPARTMENT**