

South Carolina Law Enforcement Division - Status Records



Date Range From 01/01/2009 To 04/15/2010
DataMaster (BAC/DMT) Serial Number - 118207
Report Date - 4/15/2010

Legend I -
Incomplete
R -
Refusal
V -
Invalid
Sample
X -
Interference
Detected

<u>Serial Number</u>	<u>Loc Number</u>	<u>Date/Time</u>	<u>Status Record</u>	<u>Status Info</u>
118207	SC0100000	2/10/2009 9:56:30 PM	BLANK ERROR	
118207	SC0100000	2/13/2009 2:48:49 AM	INTERFERENCE DETECTED	
118207	SC0100000	2/26/2009 3:33:39 AM	INTERFERENCE DETECTED	
118207	SC0100000	3/8/2009 5:01:03 AM	INTERFERENCE DETECTED	
118207	SC0100000	3/9/2009 4:53:17 PM	INTERFERENCE DETECTED	
118207	SC0100000	3/9/2009 5:20:08 PM	INTERFERENCE DETECTED	
118207	SC0100000	3/10/2009 5:34:15 PM	INTERFERENCE DETECTED	
118207	SC0100000	3/10/2009 5:48:13 PM	INTERFERENCE DETECTED	
118207	SC0100000	3/10/2009 6:41:26 PM	INTERFERENCE DETECTED	
118207	SC0100000	4/1/2009 2:34:31 AM	INTERFERENCE DETECTED	
118207	SC0100000	6/3/2009 2:22:16 AM	RFI DETECTED	
118207	SC0100000	7/12/2009 10:42:14 PM	PUMP ERROR	
118207	SC0100000	7/14/2009 11:35:49 PM	EXTERNAL STANDARD OUT OF RANGE	
118207	SC0100000	7/18/2009 3:03:24 AM	COMMUNICATION ERROR	
118207	SC0100000	7/19/2009 12:43:57 PM	RFI DETECTED	
118207	SC0100000	7/21/2009 1:37:02 AM	EXTERNAL STANDARD OUT OF RANGE	
118207	SC0100000	7/26/2009 10:22:01 PM	EXTERNAL STANDARD OUT OF RANGE	
118207	SC0100000	8/15/2009 1:15:33 AM	INVALID SAMPLE DETECTED	
118207	SC0100000	8/15/2009 11:42:59 PM	BLANK ERROR	
118207	SC0100000	8/19/2009 3:37:41 AM	COMMUNICATION ERROR	
118207	SC0100000	8/21/2009 12:07:53 AM	RFI DETECTED	
118207	SC0100000	9/3/2009 11:30:43 PM	RFI DETECTED	
118207	SC0100000	9/6/2009 10:19:54 PM	INVALID SAMPLE DETECTED	
118207	SC0100000	9/6/2009 11:07:48 PM	EXTERNAL STANDARD OUT OF RANGE	
118207	SC0100000	10/2/2009 8:34:07 PM	BLANK ERROR	
118207	SC0100000	10/7/2009 1:28:17 AM	COMMUNICATION ERROR	
118207	SC0100000	10/15/2009 5:55:50 PM	EXTERNAL STANDARD OUT OF RANGE	
118207	SC0100000	10/16/2009 3:30:40 AM	PUMP ERROR	
118207	SC0100000	10/29/2009 2:46:27 AM	COMMUNICATION ERROR	
118207	SC0100000	11/3/2009 8:15:54 PM	EXTERNAL STANDARD OUT OF RANGE	
118207	SC0100000	11/6/2009 10:29:39 PM	COMMUNICATION ERROR	
118207	SC0100000	11/21/2009 12:19:09 AM	INVALID SAMPLE DETECTED	
118207	SC0100000	11/22/2009 12:42:24 AM	SUCK BACK ERROR	

118207	SC0100000	12/16/2009 1:50:39 AM	RFI DETECTED	
118207	SC0100000	12/16/2009 2:56:21 AM	COMMUNICATION ERROR	
118207	SC0100000	1/15/2010 3:02:33 AM	COMMUNICATION ERROR	
118207	SC0100000	2/21/2010 12:28:17 AM	BLANK ERROR	
118207	SC0100000	2/27/2010 12:47:44 PM	INVALID SAMPLE DETECTED	
118207	SC0100000	2/28/2010 2:59:14 AM	RFI DETECTED	
118207	SC0100000	3/6/2010 2:03:45 AM	BLANK ERROR	
118207	SC0100000	3/7/2010 12:35:28 AM	COMMUNICATION ERROR	
118207	SC0100000	3/26/2010 12:14:43 AM	INVALID SAMPLE DETECTED	
118207	SC0100000	4/10/2010 10:00:58 PM	BLANK ERROR	

THIS REPORT REPRESENTS TRUE AND CORRECT COPIES OF THE ORIGINAL DOCUMENTS MAINTAINED BY SLED IN THE NORMAL COURSE OF BUSINESS.



**DEBORAH H. BANKS, LIEUTENANT
SUPERVISORY SPECIAL AGENT
IMPLIED CONSENT DEPARTMENT**